

MODU CODE

Code for the construction and equipment of Mobile offshore drilling units, 2009

2010 Edition

Errata


On page 75, paragraph 5.6.9, add a footnote after "...flame-retarding properties.".*

On page 77, paragraph 5.7.6, delete the second sentence so that the amended paragraph reads as follows:

"5.7.6 Audible signals in high noise areas should be supplemented with visual signals."

On page 143, amend the second footnote by adding "as amended" after "A.802(19),".

On page 168, replace the drawing “Figure 13-4 – Obstacle-free sector marking” with the figure below:



On page 172, subparagraph 13.5.26.8, amend “less than” to read “more than”.